




DAVID EVANS
AND ASSOCIATES INC.

COURTHOUSE SQUARE FLOOR DEFLECTIONS 11-24-2008 JGW




NOTES:

1) Survey data is from survey conducted by David Evans and Associates' JKB and DDB (surveyors' initials) from 10-24-2008 to 11-21-2008. The survey was conducted with a water-level manometer.

2) A negative value ([-X.X"]) indicates upward deflection

3) A positive value ([X.X"]) indicates downward deflection

0 5 20
SCALE



Marion County
OREGON
BUSINESS SERVICES
Facilities Management

FACILITY:

**COURTHOUSE SQUARE
SECOND FLOOR**

FILE NAME:
CS2.dwg


BLDG PLAN DATE:

CS-2



DAVID EVANS
AND ASSOCIATES INC.

COURTHOUSE SQUARE FLOOR DEFLECTIONS 11-24-2008 JGW




NOTES:

1) Survey data is from survey conducted by David Evans and Associates' JKB and DDB (surveyors' initials) from 10-24-2008 to 11-21-2008. The survey was conducted with a water-level manometer.

2) A negative value (-X.X\") indicates upward deflection

3) A positive value (X.X\") indicates downward deflection



Marion County
OREGON
BUSINESS SERVICES
Facilities Management

FACILITY:
**COURTHOUSE SQUARE
THIRD FLOOR**

FILE NAME:
\\bldg\cs\cs3

BLDG PLAN DATE:


CS-3



DAVID EVANS
AND ASSOCIATES INC.

COURTHOUSE SQUARE FLOOR DEFLECTIONS

11-24-2008
JGW



NOTES:

1) Survey data is from survey conducted by David Evans and Associates' JKB and DDB (surveyors' initials) from 10-24-2008 to 11-21-2008. The survey was conducted with a water-level manometer.

2) A negative value (X.X") indicates upward deflection

3) A positive value (X.X") indicates downward deflection



Marion County
OREGON
BUSINESS SERVICES
Facilities Management

FACILITY:

COURTHOUSE SQUARE
FOURTH FLOOR

FILE NAME:
CS4.dwg


BLDG PLAN DATE:

CS-4



DAVID EVANS
AND ASSOCIATES INC.

COURTHOUSE SQUARE FLOOR DEFLECTIONS 11-24-2008 JGW



NOTES:


1) Survey data is from survey conducted by David Evans and Associates' JKB and DDB (surveyors' initials) from 10-24-2008 to 11-21-2008. The survey was conducted with a water-level manometer.

2) A negative value ($-X.X''$) indicates upward deflection

3) A positive value ($X.X''$) indicates downward deflection

4) $X.X''$ Indicates measured deflection from survey conducted on 6-06-2007

20
SCALE
0 5



Marion County
OREGON
BUSINESS SERVICES
Facilities Management

FACILITY:

COURTHOUSE SQUARE
FIFTH FLOOR

FILE NAME:
CS5

BLDG PLAN DATE:

CS-5